

Water Therapy Major Upgrades / Repairs Completed for 2010

Head Seal Gaskets – forward and aft
Starter Batteries Replaced – 3
Engine Control Unit – Main Helm Station
Large Fenders Replaced – 2
Anchor Lines Replaced – 1
Bedroom Fans Replaced – 4
Beach Flood Lights Replaced / Repaired – 1
Hull Acid Washed / Alumibrite Applied
Holding Tank Treated
Interior Carpet Steam Cleaned
Swim Platform Handbar Railing Repaired
Kitchen Items Replaced or Purchased (knives, pots/pans.....)
Inverter Repaired
Flat Panel TV installed – Main Salon / Upper Forward Birth
Storage Drawers Added Below Flat Panel – Main Salon
Upper Deck Carpet Replaced
Toy Tank Fuel Hose Replaced / Flex Joint Added at Handle
Toy Tank Dip Stick Replaced
Charging System Rewired in Engine Compartment
Upper Deck Cushions Repaired / Replaced
Fishing Pole Holders Added – Rear Deck
Reading Lights in Lower Births Repaired
Broken Lint Filter on Dryer Replaced
Fridge Drawers Replaced
Forward Head Holding Tank Reader Repaired
Lake Water Pump Replaced
Screen on Forward Door Replaced
Curtain Rod / Hangar Repair – Births / Main Salon
O2 Sensor Replacement – 2
Plug Replacement Forward Deck Port Side
Winch Control Handle Repair
Forward Bath Sink Faucet Repair
Main Salon Mantle Seal
DVD Player Repair from Water Leak
Air Vent Repair in Hold
Main Hold Bilge Pump Fuse Repair / Replacement
Exterior Deck Carpet Cleaned X 2
Wax Exterior Above Main Deck
Bilge Cleaned X 2
Broken iPod Docking Station Replaced – Main Helm
Rewired to Add XM to Main Stereo
Replaced 2 Batteries in Engine Compartment
Repaired Steering Linkage
Engine and Generator Major Service Completed
Rebuilt Outdrives – One outdrive require new components
Replaced Isolators in Engine Compartment
Replaced Gen Light ON Light at Helm
Wash Down Hose Leaks Fixed
Wash Down Nozzles Replaced
Replaced Upper Deck Trash Can
Replaced Prop Wrench