

# Fixed or Replace 2011

- Bilge Blower
- Engine Compartment Battery Charger Isolators
- 2 Inverter Batteries replaced
- 4 House Batteries / Battery Box's
- Winch Remonved, Rebuilt and Re-Installed
- 8 Outside Chairs
- 2 Holding Tank Plumbing Rebuild – Finish repair in Jan/Feb
- Fly Bridge Switch Cover (Accuator) Replacemed
  - Additional covers purchased. Remaining will be replaced in Spring
- 2 Toilet Seats
- LCD Stairway / Swim Platform Lighting
- 600 Foot Spool of ¾ Inch Gold Anchor Line
- Henkle 4 Star Tomato Knife Tip bent – straightened and filed
- Missing pearing knife - replaced
- Missing Fender - replaced
- Kitchen Sink Faucet spray and stream function not working - fixed
- Stove Center Burner Knob not attached and part missing – fixed
- Toy Tank Hose badly kinked – Will be replaced in Spring
- Swim Platform Caked with Red Clay and Mildew – Power Washed and Cleaned
- 120 V Hoist Not Functioning – removed and taken for repair
- 120 V Plug Plate – replaced
- Hoist Securing lines - installed
- Damaged Anchor Line – Cut and whipped (2 smaller pieces)
- 4 NEW Anchor Lines put in main hold – Whipped and wrapped.
- Aft Bath Fresh Water Faucet leaking – replaced
- Couch – Applied Fabreeze
- Fresh Air Return for Air Handler Reattached
- Fresh Air Return tubing for Air Handler torn and leaking – repaired
- Lysol treated Fresh Air Return
- Aft Toilet Seat broken – replaced with new
- Forward Toilet Seat cracked – replaced with new
- Fore and Aft Bathrooms - Installed new Auto Air Fresh Dispensers
- Lower Berth (fore and aft) Reading Lights broken – replaced with new
- Aft Screen Sliding Door Screen coming out – repaired
- Forward Screen Door Lock won't Lock – lock replaced with new
- Rewired and rerouted house batt wires
- Exterior 12V Lights replaced
  - Forward Step to Upper Deck – 1
  - Aft Step to Upper Deck – 3
  - Swim Platform – 3

- Exterior 12V LED Lights Purchased to Replace Bulb Lights – Stair and Swim Platform – Install in Spring
- Upper and Lower VHF Radio Upgraded
- Swim Platform Rub Rail detached and sagging into water – repaired
- Buzzing in speakers when using XM radio and Gen is running – installed inline noise filter / fixed
- Straightened wiring in helm station
- Stereo Head unit not driving speakers – repaired (reset button behind head unit plate)
- Curtain parts broken – repaired
- Forward Hold STINKS – Cleaned / Dried / Straightened
- Main Hold – Straighten / deodorized
- Fore and Aft doors dirty / sand in tracks – cleaned
- Slide water feed hose loose – re secured
- Microwave filters and parts greasy – disassembled and cleaned
- Stovetop heavily soiled – cleaned
- Forward Bath Sink Draining SLOW – disassembled drain / cleaned (YUCK)
- Several Deck Chairs cracked or broken – replaced with metal frame chairs (4 lower deck / 4 Upper deck)
- Dead Man Cooler missing – replaced (forward hold)
- VHF radio microphone holder (upper and lower helm stations) broken – replaced
- 5 Gal Water Dispenser / sand and debris in upper water unit – disassembled and cleaned
- Dryer Vent Cleaned
- Gen Raw Water Pickup Strainer - cleaned